ON-SITE WASTEWATER SECTION

PROPERTY ID #: [illegible]
COUNTY: Iredell

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Phyllis Jones
ADDRESS: 117 Travertine LN
APPLICANT:
PROPOSED FACILITY:
APPLICATION DATE:
DATE EVALUATED: 3/17/99
LOCATION OF SITE: Travertine LN
PROPOSED DESIGN FLOW (.1949): 360
PROPERTY SIZE: 500
PROPERTY RECORDED:
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | LSS | 1-24 | Fr-Fi SBK/C | NEXP, NS | | | | | PS .3 |
| | | 24-48 | Fr-Fi SBK/CL | NEXP, NS | | | | | |
| 2 | LSS | 1-28 | Fr-Fi SBK/C | NEXP, NS | | | | | PS .3 |
| | | 28-48 | Fr-Fi SBK/CL | NEXP, NS | | | | | |
| 3 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| ailable Space (.1945) | 1200 | 1200 |
| tem Type(s) | Grav./Conv. | Grav./Conv. |
| LTAR | .3 | .3 |

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: J.M. Morgan
OTHER(S) PRESENT: