IREDELL COUNTY HEALTH DEPARTMENT

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: Hope Brothers DATE REQUESTED: 7-29-80

ADDRESS: Iredell PLAT NO.: Lot 5 Love Property

COUNTY: Iredell LOT SIZE: 100x230

LOCATION OF SITE: 21N across from Vondeen Bang United Methodist Cemetary (on left before 2390)

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U 2-4%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S (PS) Clay U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S (PS) Clay Subangular U	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS 48+ U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	S PS None observed U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) PS No Mottles U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS Slow U	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*	Creek			
SOIL SERIES	PS			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments: _____

Described By: [illegible]

Title: S.I. Date: 7-29-80

DHS Form 2601 (2/77)
Sanitation