4659 48 2037

07577

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Larry J. White DATE Nov 5 87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21 N. TR 5R 2390 (Westmoreland) TL towards Hiwassee Bear Ct. on left before bottom of hill S. R. No. _____

SUBDIVISION NAME Cedarhill Acres LOT NO. 16 SECTION OR BLOCK NO. _____


House ( ) Mobile Home ( ) Business ( ) Other ~~Addition~~ (frame in bedroom plumbed in basement w/Addition)

No. Bedrooms ~4 No. Bathrooms ~3

Garbage Disposal Unit	Yes ( )	No ( )	Character & Porosity of Soil _____
Auto. Dishwasher	Yes ( )	No ( )	Percolation Rate _____
Auto. Wash. Machine	Yes ( )	No ( )	Topography _____
Site Suitable	Yes ( )	No ( )	Depth to Water Table _____
			Rock or other impervious formations _____

Lot Area Existing

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank Existing Gals.

Nitrification Field:

No. of Lines Existing

Sq. Ft. _____ Linear Ft. _____

Depth of Stone in Lines _____

Water Supply: Individual ( )

Public (✓)

Community Well

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Existing system showing no sign of malfunction at time of inspection.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: D. K. Hinson / RS DATE 11-5-87

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold