DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: George Church
ADDRESS: 115 Sandstone Lp.
APPLICANT: ___
APPLICATION DATE: ___
DATE EVALUATED: 3/4/01
PROPOSED FACILITY: ___
PROPOSED DESIGN FLOW (.1949): ___
PROPERTY SIZE: ___
LOCATION OF SITE: ___
PROPERTY RECORDED: ___
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	270 T Rear	0-6	mm sbk | cl	FR SS-SP	P R				
		7-29	MM sbk | cl MVC	FR SS-P	P R				
		30-49	MF sbk GR | l SAP	FR SS-NP	P 4R				.35
2	270-315 T Rear	0-29	mm sbk cl	MVCL FR SS-SP	4R				
		30-48	MF sbk | cl SAP	VFR SS-SP					
3	270 T Front	0-7	mm GR sl	FR SS-SP	P R.				
		9-29	MF sbk | scl	FR SS-NP	P				
		30-49	MF GR | l SAP	VFR SS-NP	P | 4R				
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	?	
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): New Well
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: Rebecca Hogan (93) Spencho
D. Church