13341

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Daniel Wilhelm DATE Oct. 9, '91 PERMIT NO. 40-1-A-14/15

PHONE: Business _____ Home _____

LOCATION 115-21 N TR 2389 (Shepherd Rd.) ~½ mile TL into Shepherds Field on Right S. R. No. _____

SUBDIVISION NAME Shepherds Valley LOT NO. 15 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes ( ) No (✓)

Auto. Wash. Machine Yes (✓) No ( )

Site ~~Suitable~~ RS Yes (✓) No ( )

Lot Area ½ Ac +

Character & Porosity of Soil firm ps clay


Percolation Rate 3-35

Topography 6-10%

Depth to Water Table 41+

Rock or other impervious formations some small scattered rock

_____ Basement with Plumbing _____ Basement without Plumbing Repair Area ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 6

Sq. Ft. 1080 Linear Ft. 360

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Larry Beam

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY DR Hmorn, RS. DATE 10-9-91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold