IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Woodbury Boy Scout Patch DATE 6-21-76 PERMIT NO. 760

PHONE: Business _____ Home _____

LOCATION 115 21 N on Right behind Church

_____ S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House ( ) Mobile Home ( ) Business ( ) Other Boy Scout Patch

No. Bedrooms — No. Bathrooms 1

Garbage Disposal Unit Yes ( ) No (X)
Auto. Dishwasher Yes ( ) No (X)
Auto. Wash. Machine Yes ( ) No (X)
Site Suitable Yes ( ) No (X)

Lot Area Acreage

Character & Porosity of Soil Clay Loam
Percolation Rate 45 Min
Topography Rolling
Depth to Water Table 10 Ft
Rock or other impervious formations None



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10 in
Water Supply: Individual (X)
Public ( )

Installed by Hoard & Septic Tank

IMPROVEMENTS PERMIT BY John Houston

COMMENTS: _____

CERTIFICATE OF COMPLETION BY John Houston DATE 6-21-76

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

RIDDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System 25 TAC Chapter 285 Article 1300)

OWNER OR CONTRACTOR Barbarbus Boy Scout Hatch DATE 4-21-76 PERMIT NO 113

PHONE Business _____ Home _____

LOCATION 1/2 mi North on Rte 6 behind Church

S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business ( ) Other Boy Scout Hatch

No. Bedrooms 3 No. Bathrooms 1 Character & Porosity of Soil Clay loam Poor


Garbage Disposal Unit Yes ( ) No (X) Percolation Rate 80 min to 1 in

Auto. Dishwasher Yes ( ) No (X) Topography 2-3% Slope

Auto. Wash Machine Yes ( ) No (X) Depth to Water Table 10 ft

Size Suitable Yes ( ) No (X) Rock or other impervious formations None

Lot Area 2 acres



Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 625 Linear Ft. 250

Depth of Stone in Lines 10

Water Supply: Individual (X)

Public ( )

Installed by _____

Plot or System

IMPROVEMENTS PERMIT BY _____

COMMENTS _____

CERTIFICATE OF COMPLETION BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Harbuck Log Cost Hist DATE 4-21-76 PERMIT NO. 113

PHONE: Business _____ Home _____

LOCATION US 21 North on Rt of Behind Ford

S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House ( ) Mobile Home ( ) Business ( ) Other Log cost hist

No. Bedrooms — No. Bathrooms 1

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes ( ) No (✓)
Auto. Wash. Machine Yes ( ) No (✓)
Site Suitable Yes ( ) No (✓)

Lot Area Large

Character & Porosity of Soil Clay loam
Percolation Rate Not taken
Topography Side hill
Depth to Water Table 10 FT
Rock or other impervious formations None



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 225 Linear Ft. 250
Depth of Stone in Lines 10
Water Supply: Individual (✓)
Public ( )

Installed by _____

IMPROVEMENTS PERMIT BY John Houston

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold