DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 71 Brookside ph 2 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-10	BSCL GR	FRF SSSP	- common YB Matrix from 26-38" 2 chromas @ 26"				(4) 26-38" @ 46-56"
		10-28	YBCL ABK	FF SP					
		28-46	BCL WSBK	FR SSSP					
		46-56	SL SAP	MFR SSSP	26"	.1025-.15 LPP	.25	.3	
2		0-6	BSCL GR	FRS SSSP	SP 2 chromas @ 16"				(4)
		6-18	YB/GC ABK/Platy	FI, Mo FI					
		18-39	B/CL MFSBK	FI SSSP					
		39-48	SL SAP	FR SSSP					
3		0-10	BSCL GR	FR SSSP	— .25				
		10-20	P/YBCL ABK	FI SP					
		20-32	MFSBK CL	FR SSSP	— .3				
		32-48	SL SAP	FR NSNP	— .4				
4		0-8	gr sdy brn scl	fr sss sp					.25
		8-33	m-vfsbk rd/brn c	fr sp fr ss/p					.4
		33-55	SL SAP	fr ss/NS-sp-np					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 2-19-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 71 Phase 2 Brookleaf continued PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
5		0-6	WF SiLbrnsgcl	fr sssy					
1		6-19	AB WF c	fr sb					
		19-31	WF sicl rdc	fr ssscp common in Bmp					.25
		31-60	mottled SLSCP	fr NSNP					.4-.5
6		0-6	wk sicl brnsdl	fr ssscp					
2		6-24	SiCL RdBrnc	fr sst Common Fe Mn					.25-.3
		24-59	mottled SLSNP	NSNP					.4-.5
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____