DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 2-18-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 68 ohs 2 Sandpiper PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-7	wksmk BSL	sl fr ss sp					.3
		7-24	SAb RC	fi-fr sp few prominent					
		24-45	wk sab rcl	common sl fr ss sp					
		45-60	many 3/sap	fr ss sp					
2		0-6	vsm BSL	fri sss p	2 chroma @ 18-28"				
		6-20	SAP/Ath RAC	fi sp -					
		20-36	wsm/ RYLL	fi sp -					
		36-52	sl SAP	fri sss p					
3		0-10	gn-brn sdl	fr ss sp					.1-.125 @ 18"
		10-30	wk sab/hybrid	c seq/mixed	fr ss sp				
		30-48	massive cl	many gley, few ch, 2 matrix	30"-48"				
		48-52	LS sap						
4		0-8	gn brn sdl	fr ss sp					U
		8-19	m-wk sab	c fr sp					
		19-45	wk AB/sab RCL	fi sss p	20"-48"				
			common y brn mottles	few common chs					
			appear to be getting out of matrix at bottom of pit						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 2-19-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 68 ph 2 Brookview (continued) PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
5		0-8	wksbk brn scl	fr ssp					
		8-45	AB YR-Abrpt c	fi sp	16/18"				4
		45-60	wk sbk rdbr	fr ss sp	common med sap				
				appears later 45"+					
6		0-7	wksbk brn scl/cl	fr ss sp					
		7-25	sbk rc	fr wd sap fr sp ss sp					.4
		25-63	90% massive sl sap	fr cl ns sp np					
7		0-5	wksbk brn scl	fr ss sp					
		5-18	sbk rc	fi fr ss sp					.3
		18-42	wksbk cl	fr ss sp	common med sap				
		42-59	sl sap	fr ss sp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____