COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 2-21-02
LOCATION OF SITE: Lot 98 Sec 2 Brookwood PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-11	gr brn sl/scl fr ss sp						
		11-17	SAB RCL fr ss sb						
		17-40	wk RB RC fi sp		common brn mottles Hor 2 18-40"				(U)
		40-61	LSAP fr ss sp					Sap looks good	
2		0-9	gy-wk SAB brn scl fr ss sp		24"-39"				
		9-16	SAB RCL fr ss sp						
		16-39	wk RB RC fi sp		common brn mottles Hor 2				(U)
		39-52	wk SAB R-yel common inf sap fr ss sp					Looks ok 7.5Y"	
3		0-8	gy-wk SAB brn scl fr ss sp						
		8-16	SAB RCL fr ss sp		16"-35"				
		16-38	wk RB RC fi-fri sp		common brn Hor 2				<38" (U)
		38-63	wk SAB yel-brn common inf sap					7.5YR 5/3	
4		0-6	gy-wk SAB brn scl/scl fr ss sp						
		6-21	SAB RC fi-fri sp		Sap				-3
		21-51	mod-SAB R-yel-brn common inf sap fr ss sp						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 2-22-02
LOCATION OF SITE: Lot 95 continued from 2 Knotts Ln PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
3		0-5	gr-wk sab brn sd	fr sss p					.225-.25
1		5-24	sab/AB R brn	c fr sp-sss p	common brn mottles				-3
		24-47	wk fsab R cb	common mi beg fr sss p					
					Crystall @ 36" TD based on This pit				
6		0-4	wk sab brn	sd fr sss p					
2		4-15	sab R C	fr sp sep fr sss p					o3
		15-53	wk fsab R cb	common-many mi beg sap					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____