DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 2-24-22
LOCATION OF SITE: Lot 99 phs 2 Brooke PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8	wk sab bsl scl	frssp					.25 - .3
		8-19	mwk sab rbnl sc	fi sp ss sp					
		19-40	wk sab rcl common mi	sp fr ss sp					
		40-57	Stone LSap	fr ss sp					
2		0-7	g-wk sab bsl scl	fr ss sp					.3
		7-10	wk mb rbnl c	fr sp					
		10-15	wk sab rcl common mi	sp fr ss sp					
		15-40	LSap	fr ss sp					
		40-62	sl sap	fr ss-ns sp					
3		0-7	g-wk sab bsl scl						.25 - .3 = .4
		7-16	sab RC	fi sp					
		16-33	mi sab R-gr cl	fr-common mi sp fr ss sp					
		33-59	LSap	fr ss sp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____