VISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 2-18-02
LOCATION OF SITE: lot 60 ph 2 Meadowlow PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8	gr-wk sab brn scl	fr sss p	27"+ 6" water in bottom of pit				.1-.125 LPP
		8-27	sab r-pbrn c/cl	fr sp-ssp					
		27-50	wk fab mixing ybrn sc/fr sp						
2		0-8	gr-wk sab brn scl	fr ssp	40"+				.25 @ ≤28"
		8-33	fri sab rc	fr sp					
		33-50	wk fab r-yb cl	common ybrn mottles few clay fr					
3		0-8	gr-wk sab brn scl	fr sss p					.25
		8-26	sab red	fr sss p					
		26-48	m-wk fab rc	fr sp stky few ybrn mottles					
4		0-7	gr-wk sab brn scl	fr ssp	26"+ becoming gleyed @ 36"+				LPP .1
		7-45±	wk sab/fab pbrn-ybrn scl	fi-fr sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 2-19-02
LOCATION OF SITE: Lot 60 Phase 2 Brookstone (continued) PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
5 / 1		0-12	WSL BSCL	fr SSSP	few YB @ Bottom of Horizon - common YB 2 chroma @ 46"	TB 24"			PS .25
		12-36	MFSBK RCL	fr SSSP					
		36-53	MWSBK RB/YB SC	fr SSSP					
6 / 2		0-6	DSCL GR	FRJ SSSP					PS .3
		6-18	SBK/MSBK RC	FJ SP					
		18-47	MSBK RCL	fr SSSP					
7 / 3		0-4	GR BRNSCL	fr					.2-.25
		4-51	AB YR C	fisp common-many fine manganese coatings/stains					
8 / 4 SFE 59A		0-3	GR/WSBK BSCR	fr SSSP					PS .3
		3-10	SBK RB+C	fi SSSP					
		10-20	MFSBK RCL	fi SSSP	common SAP				
		20-35	WSBK RSAP	fr SSSP	few clinc				
		35-60	VSAB/M YB LSAP	fr SSSP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

SFE 59A 9) 0-7 BSCL GR fr SSSP
4-10 RC MM fr SP
10-34 WSBK RCL fr SSSP common SAP .3
34-58 SL SAP fr SSSP