DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ____ APPLICATION DATE ____
ADDRESS: ____
PROPOSED FACILITY: ____ PROPOSED DESIGN FLOW (.1949): ____ DATE EVALUATED: 2-22-02
LOCATION OF SITE: Lot 121 phs 2 Brook blw PROPERTY SIZE: ____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ____ PROPERTY RECORDED: ____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-3	wk sgb brn sdl	fri ssp					.3
		3-21	sgb rc/cl	fri ssp					
		21-52	wk fsbk/gr yel/brn gr L sdy	fri ssp					
2		0-3	wk sgb brn sdl						.3
		3-13	sbk cl/cl	fri ssp					
		13-30	wk sbk rd/cl	common mica ssp fri ssp					
		30-55	LSsp	fri ssp					
3		0-5	wk sgb brn sdl	fri ssp					.3
		5-16	sbk rc	fri sp					
		16-28	mod sbk yel/rd	common mica ssp fri ssp					
		28-57	gr-massive L/sdl	sap fri ssp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): ____
EVALUATED BY: ____
OTHER(S) PRESENT: ____

COMMENTS: ____