DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 2-19-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 77 Phase 2 Fawn Lake PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSIST NCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-26	gr brsl lfs ch fr sss p						.4
		26-36	BSAb rcl	fr ss sbp					.25
		36-45	wk SAb rcl few ill sap		many low matrix				
		45-53	massive SL sap	fr sss p					
2		0-24	BSL br	fri sss p					PS
		24-43	YR/RBC ABK	fr sl -	many YB mottles				.2 -
		43-54	ABK/WSBK YRCL	fr sp/sss p					.25
3		0-18	br BSL/SCL	fr sss p					
		18-33	mw SBK RBC	fr/fri sp -	lt B mottles				.25
		33-58	wk SBK/ABK YR CL	fr sss p -	common sap				
		58-74	SL SAP m	fr sss p/ns np					.3
4		0-14	gr-wk SAb brN sl fcl	fr sss p					
		14-25	SAb rcl cl	fr sss p					.25+
		25-42	WK AB RY SCL	common - many red/ sep/common/ few - common	clay				4
		42-60	Massive heavy SL SAP	fr ss ns sp np					
			looks like good sap	or LRP site					

1-.125 LRP

1 of 1948D

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____