DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 2-19-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: 104 Brookglen phs 2 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	in between 2 Burns pedons	0-8	BSL WSBK	FR SSSP				Few 2 strong @ 25-34	(4) 2 .1 LPP .125 1945d
		8-32	SBK RC	FR S, P/SSSP. few YB mottles - common					
		32-45	WFABK SCL	FI SS SP					
		45-57	M SCL SAP	FR SS SP				South 4A site of Pit	
2	2-21-02	0-8	gy-wk SAB brn scl	fr sss p					.3
		8-26	SAB RC common mi lam	fr sss p					
		26-62	wk fms - massive RY LSAP	fr sss p					
3	2-21-02	0-6	gy-wk SAB brn scl	fr sss p					.3
		6-28	SAB rc/cl	fr sss p SETP					
		28-60	wk SAB - massive yR - RY LSAP	fr sss p					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____