DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 3-1-02
LOCATION OF SITE: lot 81 sec 2 Brookwood PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-8 | gr brsl fsl | | | | | | 3 |
| | | 8-22 | SCL | fr | | | | | |
| | | 22-35 | mSCL | fr common mica SAP | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 2 | | 0-8 | BSL | fr SSSP | | | | | 5 |
| | | 8-24 | SAB | fr SSSP | | | | | 3 |
| | | 24-40 | MFSAB | fr SSSP | | | | | |
| | | 40-65 | SL SAP | fr SSSP | | | | | |
| | | | | | | | | | |
| 3 | | 0-8 | MSL | fr SSSP | | | | | 5 |
| | | 8-26 | SAB | fr SSSP | | | | | 3 |
| | | 26-59 | LSAP | fr SSSP few clinc. | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 4 | | 0-21 | BSL | fr SSSP | | | | | 5 |
| | | 21-33 | RL | fr SSSP | | | | | 3 |
| | | 33-60 | RL | fr SSSP | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

5) 0-8 SSL fr SSSP
8-25 SBK RC/CL fr SSSP
25-48 weak RCL fr SSSP SAP common 3
48-64 LSAP fr SSSP