IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Sam A. Boone Inc DATE 2-14-86 PERMIT NO. 66

PHONE: Business _____ Home _____

LOCATION 1155 To 1138 (Presbyterian Road) 1½ mile on R

S. R. No. _____


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business (X) Other 50'X100' WAREhouse

No. Bedrooms _____ No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (X)	Character & Porosity of Soil	Silty clay - p.m
Auto. Dishwasher	Yes ( )	No (X)	Percolation Rate	0.5 gal/ft 24 hrs
Auto. Wash. Machine	Yes ( )	No (X)	Topography	2 to 10%
Site Suitable	Yes (X)	No ( )	Depth to Water Table	4'
Lot Area 2+ ACRE			Rock or other impervious formations	NONE OBS

_____ Basement with Plumbing _____ Basement without Plumbing X No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 600 Linear Ft. 200
Depth of Stone in Lines 12"

Water Supply: Individual (X)
Public ( )

Installed by Larry Boone

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

3'X67'
3'X67'
3'X67'

IMPROVEMENTS PERMIT BY Fred Clemmer

COMMENTS: Fit Old fill material

CERTIFICATE OF COMPLETION BY Fred Clemmer DATE 2-14-86

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold