IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Larry Ligo DATE Apr. 20, '79 PERMIT NO. 104

PHONE: Business _____ Home _____

LOCATION 1125 S to stop sign TR. go ~½ mi. TR on dirt drive at end

SUBDIVISION NAME _____ S. R. No. _____

LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other Addition to Photographic Studio w/ 1 bathroom

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Lot Area 9 AC.

Character & Porosity of Soil Appling sandy loam
Percolation Rate —
Topography 15% +
Depth to Water Table sink.
Rock or other impervious formations sink.



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by Pete Hager

IMPROVEMENTS PERMIT BY J. C. Moore

COMMENTS: Existing system working ok at time of inspection. Photographic Studio w/ 1 bathroom to be added to system.

CERTIFICATE OF COMPLETION BY David R. Hinson DATE Apr 20, '79

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIC

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gc

9:00

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jerry Liggo

PHONE: Business _____ Home 878-8009 DATE 9-4-05 PERMIT NO. 200

LOCATION Rt 1125 Shears Chapel Rd at end TR (on L) ½ mi, TR on dirt st at end

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____ S. R. No. 1125


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Lot Area 9 acres

Character & Porosity of Soil appling sandy loam (Porosity good)
Percolation Rate 20 min 1 inch
Topography 3 to 6% slope
Depth to Water Table 10'+
Rock or other impervious formations none



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Pete Hager

IMPROVEMENTS PERMIT BY J. C. Moore

COMMENTS: remove all maple trees within 20' of septic tank system root network will clog system.

CERTIFICATE OF COMPLETION BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold