IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Larry Ligo DATE Apr. 20, '79 PERMIT NO. 104

PHONE: Business _____ Home _____

LOCATION 1125 S to stop sign TR. go ~½ mi. TR on dirt drive at end S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other Adding Photographic Studio w/ 1 bathroom

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area 9 AC.

Character & Porosity of Soil Appling sandy loam
Percolation Rate —
Topography 15% +
Depth to Water Table unk.
Rock or other impervious formations unk.



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by Pete Hager

IMPROVEMENTS PERMIT BY J. C. Moore

COMMENTS: Existing system working ok at time of inspection. Photographic Studio w/ 1 bathroom to be added to system.

CERTIFICATE OF COMPLETION BY David R. Hinson DATE Apr 20, '79

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIC

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gc

9:00

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jarry Ligo DATE 7-4-95 PERMIT NO. 200

PHONE: Business _____ Home 873-8009

LOCATION Rt 1125 Shears Chapel Rt at end TR Go ½ mi TR on dirt st at end S. R. No. 1125

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Lot Area 9 acres

Character & Porosity of Soil appling sandy loam good Porosity
Percolation Rate 2 min/inch
Topography 3 to 16% slope
Depth to Water Table 19'+
Rock or other impervious formations none



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by Pete Hager

IMPROVEMENTS PERMIT BY D. C. Moore

COMMENTS: remove all maple trees with in 20' of septic tank system must not work with city system.

CERTIFICATE OF COMPLETION BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold