4664 39 0305

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jimmy McClain DATE 3/25/87 PERMIT NO.

PHONE: Business Home

LOCATION Pheasos Chapel, Rt on Prsbeterian, Lot ~ 1/4 mile on Rt

S. R. No.

SUBDIVISION NAME COLD TRACE LOT NO. 7 SECTION OR BLOCK NO.


House ( ) Mobile Home (✓) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clayey	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	0.4 gpd	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-4% in drainfield area	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'	
			Rock or other impervious formations	None Noted	

Lot Area ~ 1 acre

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines

Water Supply: Individual (✓) in ag
Public ( )

Installed by Julian Bowles

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

Presbeterian Church Rd

IMPROVEMENTS PERMIT BY David Hinson RS

COMMENTS: System deep due to location of well.

CERTIFICATE OF COMPLETION BY [signature] DATE 3/25/87

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold