DEPARTMENT OF ENVIRONMENT,
HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

SHEET 1 OF 1
PROPERTY I.D.#: 1B-2-A-13
DATE: 1-13-96
COUNTY: IREDELL

SOIL SITE EVALUATION FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: MICHAEL BOYD
ADDRESS: 110 VISTA DRIVE
DAVIDSON, NC 28036

OWNER ✓ AGENT: PHONE: 391-4165 / 892-8246
APPLICATION DATE: 12/13/95 DATE EVALUATED 1/13/96
PROPOSED FACILITY: 3BR HOUSE W/C.S
PROPERTY SIZE: 0.9 ACRES

LOCATION OF SITE: BELLE GLADE LOT # 13
WATER SUPPLY: On-site Well ✓ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS./ SLOPE(%)	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS
1	10%	0-48	L	MFSBK	1:1/FI			.1942 Wetness Cond. S
	L							.1943 Depth/.1956 Sapr. S
								.1944 Restrictive Hori. S
								.1948 Profile Class. PS
								Profile LTAR 0.3
2	L	0-48	L	MFSBK	1:1/FI			.1942 Wetness Cond. S
	12%							.1943 Depth/.1956 Sapr. S
								.1944 Restrictive Hori. S
								.1948 Profile Class. PS
								Profile LTAR 0.3
3	L	0-48	L	MMSBK	1:1/FI			.1942 Wetness Cond. S
	35%							.1943 Depth/.1956 Sapr. S
								.1944 Restrictive Hori. S
				REPAIR AREA				.1948 Profile Class. PS
								Profile LTAR 0.3
4								.1942 Wetness Cond. -
								.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. -
								.1948 Profile Class. -
								Profile LTAR -

AVAILABLE SPACE (.1945) S OTHER FACTORS (.1946) NONE SITECLASSIFICATION (.1948) PS

SYSTEM TYPE CHAMBERED TRENCH LONG-TERM ACCEPTANCE RATE(S) 0.3 GPD/FT²

EVALUATED BY: STEVE HEDRICK OTHER(S) PRESENT: MICHAEL BOYD

COMMENTS: LARGE DIAMETER PIPE REPAIR AREA