DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET 1 OF 1
PROPERTY I.D.#: 1B 2A 19 & 20
PROPERTY RECORDED:
COUNTY:

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: RON WALDRON OWNER: AGENT: ✓ PHONE: 664-1490
ADDRESS: Rt Box 5 HD. APPLICATION DATE: DATE EVALUATED: 8/30/93
MOORESVILLE PROPOSED FACILITY: 3BD - 2BR CRAWL SPACE
PROPERTY SIZE: ~ 1.8 AC.
LOCATION OF SITE: Lot 19 & 20 BELLE GLADE - SHENDERS RD.
WATER SUPPLY: On-Site Well ✓ Comm. Well Public Other EVAL. METHOD: Auger Boring ✓ Pit Cut

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	LS 2%	0-4	GR l-cl	1:1	P	P			
		5-11	ABK cl	1:1	WSS-WP	P	P	I	
		12-27	WSBK cl	1:1	WS-WP	P	P	I	
		28-40	VFSBK cl C)	1:1	WS-WP	P	P	II	.25-.3
		41-	1-SAP.	1:1	WS			U	
2									
3									
4									
5									

AVAILABLE SPACE (.1945) S SITE CLASSIFICATION (.1948): P. SITE LONG-TERM ACCEPTANCE RATE: .25-.3
EVALUATED BY: SPARKS OTHER(S) PRESENT: RON WALDRON
COMMENTS: Trench bottom at 36" inches - Work only when dry - MICACEOUS
DSH - MVF,