DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet _1_
PROPERTY ID #: __Lot#
COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____Anniston, LLC_____
ADDRESS: _____Anniston Phase 3_____ APPLICATION DATE__10/6/06__
PROPOSED FACILITY: ____5-bedroom___ PROPOSED DESIGN FLOW (.1949): ___600gpd_ DATE EVALUATED: __8/06_
LOCATION OF SITE: _____Shearer's Road, Lt. on Anniston Way , Lt. Timberside Dr., Lt Hanover Dr. PROPERTY SIZE: _____ac_____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
P 99A	LSS 6-10%	0-36 36-55	RCmFABk RCvwSBk/ABk	FrSS, PSExP FiSS, PSExP	Chr 2@ 42" -few sap -few Chr 2's along root Channels @ 42"+	55"	—	42"	PS 0.25 to 42"
②	12-15% V	0-29 29-40 40-52	mwkmsbk mlsbk cl wkmsbk cl massive SL sap	frSSSp frSSSp SExP frSSSp	few common Sapwood few channels				.275
③	10% V	0-28 28-41 41-58	mmsbk c MMsblmbk cl massive LSAp	frSSSp SExP frSSSp frSSSp / few channel	few sapwood.				.3
④	10% V	0-27 27-54	smmabk cl mwkmbk cl	frSSSp frSSSp /	SExP few sapwood				.275

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): ____PS_____
EVALUATED BY: _Samuel Rollans & Brady Freeman_____
OTHER(S) PRESENT: _____

COMMENTS: