DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Pit 12-7-05

OWNER: James Rizzo
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____
LOCATION OF SITE: Creeks Edge Lot 11

APPLICATION DATE _____
DATE EVALUATED: _____
PROPERTY SIZE: _____
PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	40' from Rd. AH	0-16	1 sbk SCl	fr SS/sp/sl	32" strong gley 2 depth to wetness				U
		16-27	1 sbk c	fi ss/sp					
		27-32	1 sbk c+sap						
			32-48 soil wetness						
2	40' from rd. AH	0-10	1 sbk cl						.3 PS
		10-30	1 sbk c						
		30-48	c+sap						
3	Pit, 50' from AH	0-13	1 abk SCl		wavy no chroma 2				U
		13-26	1 abk Cl		25-30 chroma 2 to 48				
		26-38	1 abk Cl						
		38	Cl+sap						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	NO	NO
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Judy McNille
OTHER(S) PRESENT: Barry McNeely, Wesley Sparks 12-7

COMMENTS: _____