SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Curly Stotts APPLICANT:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 2/14/2002
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
LOCATION OF SITE: PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-18"	Rd/Brn C mSBK	S-SS, SP, SF, F-FR					PS
	18-48"	Brn to Gy/Brn SAP	C WE water many Fe & Common Mica Flakes					1.3
	0-18"	Brn C	W SBK SS, SP, SF, FR					
		Surface water coming into hole, Evaluation performed after weekend of rain						
		No evidence of wet soil condition via soil color						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Usable Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT: