DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Margie Ken Neiswonger APPLICANT: _____
ADDRESS: 153 Seagrove Ln M'ville APPLICATION DATE: _____ DATE EVALUATED: 3/6/97
PROPOSED FACILITY: MH PROPOSED DESIGN FLOW (.1949): 360 gpd PROPERTY SIZE: 1.1 Acre - Split
LOCATION OF SITE: Lot #27 Wildwood Acres PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-12"	SCL						.3
		12-36"	Lt C/ Heavy CL SBK	SS, SP, Fr					
		36-48"	CL Mod SBK	SS, SP, Fr					
2		0-6"	SCL		Brw				.3
		6"-24"	Lt C/ Heavy CL SBK	SS, SP, Fr	R-Brw				
		24"-48"	CL Mod SBK	SS, SP, Fr	R-Brw				
3									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Table Space (.1945)		
m Type(s)		
TAR	.3	

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): P.S.
EVALUATED BY: _____
OTHER(S) PRESENT: _____

1982 William Mark & Kathy Dillon