IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Wallace Stallings DATE 10-29-75 PERMIT NO. 238

PHONE: Business _____ Home 664-5529

LOCATION Shears Chapel Rd 3mi on ~~80~~ left

_____ S. R. No. _____


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 2
Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )
Lot Area 1.9 acres

Character & Porosity of Soil Clay loam Porosity Fair
Percolation Rate Not taken
Topography > 20% Slope
Depth to Water Table 10'+
Rock or other impervious formations none

4 System



Plot of System

Existing System
Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. ~~225~~ 225 Linear Ft. 225
Depth of Stone in Lines 1'
Water Supply: Individual (✓)
Public ( )

Installed by J. R. Bowles
installed washing machine & Bath Tub Waste water drain sys.
It was 2½' wide 133' long 16" stone

IMPROVEMENTS PERMIT BY John Houston

COMMENTS: System has Total of 358' of drain line.

CERTIFICATE OF COMPLETION BY J. C. Moore DATE 10-29-75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold