Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet:
Property ID: 4666-11-6889
Lot #:
File #: Repair
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: Tim Perry
Address: 965 Shearers Rd
Proposed Facility: Ex. SFR Design Flow (.1949) 240 GPD
Location of Site:
Water Supply: [ ] Public [x] Individual [x] Well [ ] Spring [ ] Other
Evaluation Method: [x] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [x] Sewage [ ] Industrial Process [ ] Mixed

Applicant:
Date Evaluated: 1/8/2010
Property Size: .84 AC
Property Recorded: Yes

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941		b PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
AB #1	3%	0-6	SCL,W,SBK	SS,SP,SEXP,VFR	NA				
	LINEAR	6-17	SC,M,SBK	SS,SP,SEXP,FR	NA				
		17-37	SCL,M,SBK	SS,SP,SEXP,VFR	NA				
		37-60	SSAP,MASS	NS,NP,NEXP,VFR	NA	37"	S	NA	.35
AB#2	3%	0-6	SCL,W,SBK	SS,SP,SEXP,VFR	NA				
	LINEAR	6-19	SC,M,SBK	SS,SP,SEXP,FR	NA				
		19-32	SCL,M,SBK	SS,SP,SEXP,VFR	NA				
		32-59	SSAP,MASS	NS,NP,NEXP,VFR	NA	32"	S	NA	.35

Description	Initial System	Repair System
Available Space (.1945)		S
System Type(s)		G-25% RED
Site LTAR		.35

Other Factors (.1946):
Soil Evaluation By: Ben Aldridge
Others Present: Tim Perry
Site Classification (.1948): S
Site Evaluation By: Ben Aldridge
Others Present: Tim Perry