)IVISION OF ENVIRONMENTAL HEALTH
)N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


)WNER: _____ APPLICANT: _____
.DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9-18-00
ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
OCATION OF SITE: lot 1 Grove Meadows PROPERTY RECORDED: _____
/ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-7	compacted lowsclHi SSSP						PS .2-.25
		7-24	SCL, cbrn c/cb SSSP		common yellow brown mottles				
		24-60	wk sbk type cl	fi sp sap	few brn, few mott SSP				
2		0-14	cbwscl	appears compacted 6-14 gravelly fi sSP					PS .25 @ < 40"
		14-40	YKC	mtsbk few brn mottles, few fi sap fi sp					
		40-50	scl sapprist cl						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
vailable Space (.1945)		
ystem Type(s)		
te LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____



LE ROAD 60' R\W SR #238