...ENTAL HEALTH:
...ER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

...ER: Kim _____ APPLICANT: _____
...RESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-4-00
...POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
...ATION OF SITE: lot 33 Revisit Brookfarm PROPERTY RECORDED: _____
...ER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
...LUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
...E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
#2	0-11	gr [illegible] scl	fr sss sp					PS .3
	11-26	sbk rc	fr ss sp					
	26-47	wk sbk cl	fr ss sp many mi sap					
	47-55	L many mi sap	fr ss sp					
#3	0-7	gr scl	fr sss sp	(4) 30-50 chz				
	7-34	R blky c	common f few					
	34-55	wk cl	fr ss sp many mi sap					
lot 43 hole #3	0-20	Comp SCL/ VFI						PS .3e >20"
	20-60	MWSBK cl/ICL FI/FM	SSSP Inc of Y mottles/ SAP					
lot 33 #4	0-5	vsmk sle	fr ss sss p					PS .3
	5-22	sbk [illegible]	fri ss sp					
	22-35	Wfsmcl cl	fri sss p	few SAP				
	35-50	L vsmk		Many SA				
	50-60	L SL SAP	fri SS SAP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
...able Space (.1945)		
...n Type(s)		
...TAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____