SION OF ENVIRONMENTAL HEALTH:
ITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

ER: _____ APPLICANT: _____
RESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-4-00
POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
ATION OF SITE: Lot 32 Brookleaf PROPERTY RECORDED: _____
ER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
LUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-11	gr sabl loam sc	fr sss p					PS
	11-33	sc/clay RC	fi-SD	fair/mod well/low				=25-.3
	33-56	sc/sabl cl	fi-fr ss sp					
				Boat 36"+				
	0-7	compacted	fr SP					PS
	7-14	sabl RC	fi-fr SP					.3
	14-30	m sabl loam cl	fr ss p					
	30-56	m sabl cl mn	mod fr ss p					
	0-7	compacted	fr					PS
	7-24	m sabl loam cl/c	mod fi-vfr SP					.3
	24-44	m sabl cl	fr ss p					
	44-60	sl ss p	fr ss p					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
able Space (.1945)		
n Type(s)		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____