...ISION OF ENVIRONMENTAL HEALTH:
-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

...ER: Krom APPLICANT: _____
DRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
)POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: Lot 30 Brook Glen PROPERTY RECORDED: _____
TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
'E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-6	Plow layer						PS .3
	6-13	SCL GR	FRF SSSP					
	13-32	RC/Hy CL MFSBK	FRF SSSP					
	32-56	CL WSBK	FRF SSSP					
	0-12	Plow layer						PS .3
	12-26	RC/Hy CL MFSBK	FRF SSSP					
	26-40	CL WSBK	FRF SSSP					
	0-9	BSCL GR	FRF SSSP					PS .3
	9-20	BCL WSBK	FI SP					
	20-57	RCL WFSBK	FRF/FI SST	Few Mott SAP				

ESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ble Space (.1945)		
Type(s)		
AR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____