ON OF ENVIRONMENTAL HEALTH:
E WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

ER: _____ APPLICANT: _____
RESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
ATION OF SITE: Lot 31 Brook Glen PROPERTY RECORDED: _____
ER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
LUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
upslope side of old burrow	0-16	GR/vFSL BSC	FoL SSSP					(4)
	16-36	SBK/MASS RB C/L	FRI SP/SSSP	Common YB/ few 2chromas				PS, 3@36"
	36-54	wFSBK RCL	FI SSSP					
	0-19	GR/wSBK BSCL	VFL SSSP					
	19-45	BRC SBK	FRI S, P	few YB Motels				PS
	45-58	wFSBK RCL	FI/FRI SSSP			36"-48" 76		3
	0-17	GR/wSBK BSCL	FRI SSSP					PS
	17-41	MFSBK RCL/C/L	FRI SP	few YB Motels				
	41-58	wFSBK RCL	FRI SSSP	common mica				3
	0-7	Comp BSCL	FRI SSSP					PS
	7-27	SBK CL/C	FRI SP					
	27-60	wFSBK YR CL	FRI SSSP	Few/SAP				3

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
able Space (.1945)		
n Type(s)		
TAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____