DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 4 Brook Glen PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-10	GR BSCL	FrL SSSP					PS .25
		10-25	SBK YBL	FrL SP	- mixed minor				
		25-41	WSBK RCL	FrL SSSP	- common YB mottles				
		41-58	WSBK YRSCL	FRL SSSP	Few SAP		(46" TB)		
2		0-8	GR/WSBK BSCL	FrL SSSP					PS .25-.3
		8-20	SBK RBHuCL	FrL SSSP	- common YB mottles				
		20-38	WSBK BRCL	FrL SSSP	"	"	"		
		36-51	WSBK YRCL/SCL	FrL SSSP	common SAP		(48" TB)		
3		0-15	gr wksbk brwscl	frssp					PS .25+
		15-41	SBK ybrwc	frsp	Seep				
		41-55	ypcl	common ybrw mottles frssp					
					Cobble Stone Layer				
4		0-7	gr wksbk brwscl	frssp					PS .25-
		7-27	sbk ybrwc	common ybrw mottles frsp					
		27-40	wksbk cl	fr sticky	few ybrw mottles / few SAP				
		40-51	SL/LSSP	few mn/cl frssp	Cobble Stone Layer		36"		

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____