DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Hanes Bldrs. APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12/15/03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 480 PROPERTY SIZE: _____
LOCATION OF SITE: Lot 20 HIGHLAND PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	6-7% L	0-11	SBK / scl	FR SS - SP	PS	PS			.3
		12-21	wk SBK / c	VFR SS - P					
		22-37	SBK / cl SAP	FR SS - SP					
		38-48	Fe SBK / cl MK.	FR SS - SP					
2	6-7% L	0-8	SBK / cl + O	FR S - SP	Fe + 4R 7CH 2	PS	PS		.2 .3 .3
		9-24	SBK / cl 7.5YR	Fr S - P					
		25-34	M - Fe SBK / scl	4R FR SS - SP					
		35-48	SBK / cl SAP	4R IFR SS - SP					
3		0-9	wk / scl BR.	FR S - SP	- 7R CH3 PS - 7CH3 4R U CH 2 Begins	18" MAX U	< PS	U CH 2 SPLOTCHES	.25
		10-17	M SBK / c	FR S - P					
		18-30	SBK / VH c / SAP	FR SS - SP					
		31-	M / c	FI S - P					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	U	U
System Type(s)	LPP	"
Site LTAR	.1-.15	"

OTHER FACTORS (.1946): D w/CH 2 - dissected by 1/WELL LOT 25
SITE CLASSIFICATION (.1948): U - DRAINAGE - SPACE
EVALUATED BY: Sparks
OTHER(S) PRESENT: HALSFIELD

DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 1/12/04
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: LOT 26 HIGHLAND CROSSING PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Ridge o cc	0-6	GR / sl	VFR - SS - (B)					
		7-16	SBK / cl	FR - SS - SP (R)					
		17-29	SBK / scl	FR - SS - SP	4/R.				
		30-	SBK / cl	FI S - P	CH3 4R.	u			
		31-	u		CH2 MOT				u
2	o cc	0-6	GR / scl	FR S - P	B / PS				
		7-21	SBK / c	FR - S - P.	4R/R				
		22-	u / sc	FR S . P	CH2 / 4R	u			
									u
3	u-L corner	6-9	GR / scl	VFR - SS - SP	B / PS				
		9-27	SBK / mic cl	FR mic - SS - SP	R / PS				
		28-48	mic GR/SBK mic cl SAP	FR. SS - SP	R-4R / PS		PS		.3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____