Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet: 1 OF 1
PIN #: 4668-52-3797
Lot #:
Permit #: 213108
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: DAVE SPURY
Applicant: SAME
Address: 233 OVERHEAD BRIDGE RD.
Date Evaluated: 10/9/2015
Proposed Facility: SFR
Design Flow (.1949) 480
Property Size: 4.35 AC
Location of Site: SAME
Property Recorded: YES
Water Supply: [ ] Public [X] Individual [X] Well [ ] Spring [ ] Other
Evaluation Method: [ ] Auger Boring [X] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
PIT 1	LINEAR 4%	0-14	SCL,M,SBK	NS	NA	42"	S	62"+	.375
		14-24	C,M,SBK	SS					
		24-42	CL,M,SBK	SS					
		42-62	SLSAP	NS					
PIT 2	LINEAR 4%	0-27	C,M,SBK	SS	NA	46"	S	63"+	.375
		27-46	CL,M,SBK	SS					
		46-63	SLSAP	NS					

Description	Initial System	Repair System
Available Space (.1945)	PS	PS
System Type(s)	GRAVEL	GRAVEL
Site LTAR	.375	.375

Other Factors (.1946):
Soil Evaluation By: BEN ALDRIDGE
Others Present: DAVE SPURY
Site Classification (.1948): PS
Site Evaluation By: BEN ALDRIDGE
Others Present: DAVE SPURY

479
400
OVERHEAD BRIDGE RD
438
240