ON-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Donald & Gail Blais APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 6/16/2006

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: Highland Crossing Lot #21 PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8"	Brw SCL	GR FR					PS .3
		8-33"	Rd/Brw CL	w/Few to many SAP Indus SS, SP, SE, FR & Common Mica flakes					
		33-41"	Rd/Brw CL/L	SAP Mix					
2		0-10"	Brw FSL	Rd/Brw CL & SAP Indus					PS
		10-30"	Rd/Brw CL	w/FR SS, SP, SE & Common Mica flakes to many SAP Indus					
		30-40"	CL	SAP Mix					
3		0-10"	Brw SCL	GR FR					PS .25 to .3
		10-34"	Rd/Brn to Brw CL	w/Few to many SAP Indus SS, SP, SE, FR w/Common Mica flakes					
		34-40"	Rd/Brn to Brw CL	/SAP Mix					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____