-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

'NER: _____ APPLICANT: _____
DRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-3-00
)POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: Lot 37 Brook Glen PROPERTY RECORDED: _____
TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
'E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-7	BCL GR	FR SSSP					
	7-30	RL MSSM	FR SP					PS
	30-51	BCL WSBK	FR SSSP	Many Inc of SAP @	42"			.3
	51-57	SL SAP MISS/MICA	FR SSSP					
	0-6	BSCL GR	FR SSSP	- Many Quartz Rocks				
	6-26	RC SBK/MA	FR SP					DS
	26-46	SCL WSBK	FR SSSP	- Many Inc of SAP + Quartz				.3+
	46-63	SL SAP MIS	FR SSSP	Water Coming from Quartz inclusions				
	0-10	VFSCL GR	FR SSSP					
	10-34	RC SBK	FR SP					PS
	34-46	BCL WSBK	FR SSSP	Many Inc of SAP		Many Inc of Quartz Rock through whole Profile		.3
	46-60	LSAP MISS	FR SMP					

ESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ble Space (.1945)		
Type(s)		
'AR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____