-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

...ER: _____ APPLICANT: _____
DRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-3-00
)POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: Lot 40 Brook Glen PROPERTY RECORDED: _____
TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|
| | 0-4 | BSiCL GR | FRS SS SP | | | | | |
| | 4-21 | RC SBK | FR SP | | | | | PS |
| | 21-51 | RCL WSBK | FrI SS SP | few Inc of SAP | | | | |
| | 51-63 | SL/L WSBK | FrI SS SP | | | | | 3 |
| | | | | | | | | |
| | 0-4 | BSiCL GR | FRS SS SP | | | | | |
| | 4-21 | RC SBK | FI SP | | | | | PS |
| | 21-47 | RCL WSBK | FrI SS SP | Many Inc of SAP | | | | |
| | 47-65 | SCL SBK WSBK | FrI SS SP | | | | | 3 |
| | | | | | | | | |
| | 0-5 | BSiCL GR | FrI SS SP | | | | | |
| | 5-16 | RC SBK | FR SP | | | | | PS |
| | 16-58 | RCL WSBK | F Frl SS SP | Common Inc of SAP @ 58" | | | | |
| | | | | | | | | 3 |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| ESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| ble Space (.1945) | | |
| Type(s) | | |
| AR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____