DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Nixon APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-3-00
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 44 Brook Glen PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-9	GR BSCL	FRL SSSP					PS .3
		9-20	SBK RC	FRI SP					
		20-36	WFSBK YRCL	FRL SSSP	few/common SAP				
		36-60	LSAP	FRL SSSP					
2		0-8	GR BSCL	FRL SSSP					PS .3
		8-25	SBK RC/CL	FRL SSSP					
		25-36	WSBK YRCL	FRI SSSP	Few SAP				
		36-56	LSAP	FRL SSNP					
3		0-7	comp BSCL	FRL SSSP					PS .3
		7-35	SBK BRC	FRI SP					
		35-56	CL/LSAP	FRL SSP	water bleed @ 55" common				
4		0-6	comp BSCL	FRI SSSP					PS .3
		6-24	SBK RC	FRI SP					
		24-35	WSBK RCL	FRI SSSP	com SAP				
		35-50	LSAP	FRL SSNP					
		50-61	SLSAP	FRL NSNP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____