VISION OF ENVIRONMENTAL HEALTH
N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Krom APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5/3/00
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: 6
LOCATION OF SITE: Lot 55 Brook Glen PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8	GR/vgr BSCL	FAR SSSP					PS .3+
		8-23	SPK RHy C/MC	FAR SSP					
		23-46	vgrk RCL	FAR SSSP	10YR/Hy SAP				
		46-56	l SAP	FAL SSSP					
2		0-8	GR/vgr BSCL	FAR SSSP					PS .3+
		8-24	SPK RHy C/MC	FAR SSSP					
		24-42	vgrk RCL	FAL SSSP	Few SAP				
		42-59	l SAP	FAL SSSP/NP					
3		0-5	GR BSCL	FAR SSSP					PS .3+
		5-29	SPK RHy C/MC	FAR SSSP/NP					
		29-42	vgrk LCL	FAL SSSP	Few SAP				
		42-58	l SAP	FAL SSSP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____