SION OF ENVIRONMENTAL HEALTH:
ITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

ER: _____ APPLICANT: _____
RESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
ATION OF SITE: Lot 53 Brook blvd PROPERTY RECORDED: _____
ER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
LUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-10	GR BSCL	FRL SSSP					PS
	10-39	SBK RC	FRL SSSP					
	39-58	WFSBK YRCL/L	FRL SS	common fine gSAP				3
	0-10	WSBK BSCL	FRL SSSP					PS
	10-32	SBK RC	FRL SP					
	32-55	WSBK YRCL/L	FRL SSSP	common fine gSAP				3
	0-10	WSBK BSCL	FRL SSSP					PS
	10-36	SBK RC	FRL SP					
	36-53	WSBK YRCL/L	FRL SSSP					3

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
able Space (.1945)		
m Type(s)		
TAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____