ISION OF ENVIRONMENTAL HEALTH
N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: Knox APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 4-28-00
ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
OCATION OF SITE: lot 13 Brook Glen PROPERTY RECORDED: _____
ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
		0-4	compacted scl	fi sssp					PS .3
		4-23	SAB RC	fi sp					
		23-58	wkSAB cl/L	fr sssp few common inclsp					
		0-7	compacted scl	fi sssp					PS .3
		7-21	SAB RC	fi sp					
		21-30	wkSAB cl	fi sssp					
		30-60	SL SAP	fr nsnp					
		0-22	SAB RC	fr sp					PS .3
		22-30	SAB cl	ssso few common inksap					
		30-54	scl	many inksap fr sssp					
		54-62	SL SAP	fr nsnp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
stem Type(s)		
e LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____