DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Krom APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5/3/00
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 17 Brook Glen PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-12	GR BSCL	FRI SSSP					PS .23
		12-44	RCL/CL WSBK	FRI SP/SSSP					
		44-58	MASS SCL SAP	SP	Many Red/Redd Color				
						33" TB Depth			
2		0-10	GR BSCL	FRI SSSP					PS .25
		10-33	SAK RC/LC	FRI SSSP					
		33-55	WSBK YRCL	FI SSSP	Few YB Motls (@ 35-40")				
						20" TB Depth			
3		0-8	BSCL GR/WSBK	FRI SSSP					PS .3
		8-21	SBK RTC	FRI SP					
		21-36	WSBK YRCL	FRI SP					
		36-56	MASS SAP	FRI SSSP/Firm					
4		0-5	BSCL GR	FRI SSSP					PS .37
		5-24	SBK RC/LC	FRI SSSP					
		24-50	WSBK L	FRI SSSP	Common SAP				
		50-60	SL SAP	FRI NSNP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____