...ISION OF ENVIRONMENTAL HEALTH
...SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

...ER: _____ APPLICANT: _____
DRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 4-11-00
)POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: Lot 26 Frost Glen PROPERTY RECORDED: _____
TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
'E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|
| | 0-3 | gr brn sl/scl | fr | | | | | PS .34 |
| | 3-24 | Sbk rc/cl | fr SSSP | | | | | |
| | 24-60 | SL SAP | fi SSSP Mg | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | 0-3 | gr brn scl | FRL SSSP | | | | | PS .4 |
| | 3-15 | SBK RCL | FRL SS P | | | | | |
| | 15-46 | WSBK/MBK LSAP | FRL SS SP | | | | | |
| | 46-62 | SL SAP | FRL SS NP | | | | | |
| | | | | | | | | |
| | 0-3 | gr brn scl | FRL SSSP | | | | | PS .4 |
| | 3-15 | SBK RCL | FRL SS P | | | | | |
| | 15-55 | WSBK/MBK LSAP | FRL SS SP | | | | | |
| | 55-60 | SL SAP | SS SP | | | | | |
| | | | | | | | | |
| | 0-7 | gr/brn sl BSCL | FRF SS SP | | | | | PS .3 |
| | 7-36 | MFSBK RC/CL | FRF SS SP | Inc f SAPRO 36" | | | | |
| | 36-55 | WSBK/Mas CL | FRI SS SP | Com Inc f SAPRO W Rock | | | | |
| | | | | | | | | |
| | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| ...le Space (.1945) | | |
| Type(s) | | |
| ...AR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____