...ISION OF ENVIRONMENTAL HEALTH
-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

...ER: _____ APPLICANT: _____
ORESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 4-11-00
)POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: Lot 25 Brook Glen PROPERTY RECORDED: _____
TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
'E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-6	GR/WSBK SCL	FRI SSSP					
	6-20	MASK RCL	FRI SSSP					1.3+
	20-32	WSBK YR CL	FRI SSSP	Few Fe SAP				B5
	32-60	WSBK RY CL	FRI SSSP	Common Fe SAP				
	0-3	GR BSCL/CL	FRI SSSP					
	3-18	SBK RC	FRI SP					B5
	18-36	WPSBK RCL	FRI SSSP					
	36-55	WSBK LtCl/L	FRI SSSP/NP					.3+
	0-6	GR few scl	fr SSSP					
	6-20	MASK R few cl	fr SSSP					B
	20-33	WSBK CL	fr SSSP					0.3+
	33-53	LSAP	fr SSSP					

ESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ble Space (.1945)		
Type(s)		
'AR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____