-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

NER: Krom
DRESS: _____ APPLICANT: _____
OPOSED FACILITY: _____ APPLICATION DATE: _____ DATE EVALUATED: 4-11-00
CATION OF SITE: lot 24 Brookglen PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-6	GR/wsbk scl	FRI SSSP					
	6-17	MWSBK RCL	FRI SS SP	few Inc of SAP				
	17-60	WFSBK/MBK RCL	FI SSSP	common YB motels		wetness @ 24"		4
				few 2chroma				
	0-12	Compacted CL/C VFI						
	12-56	WFSBK BRCL	FRI SSSP	few Inc of SAP				PS 3
	0-6	gr loam sbk	SSSP					PS .3 @ 52"
	6-15	SBK loam C	fr SSSP					
	15-52	wbk	cl Loam/sandy clay loam					
	52-58	yb/rd sc common mot	SP fr SP - wetness?					
	0-11	Compacted CL/C	VFI					
	11-55	RBCL w WFSBK	FRI SSSP	Few YB Motels Inc of RBCL	@ 24"			PS .25 @ less than 48"

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ble Space (.1945)		
Type(s)		
AR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____