-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

NER: Krom
DRESS: _____ APPLICANT: _____
OPOSED FACILITY: _____ APPLICATION DATE: _____ DATE EVALUATED: 4-11-00
CATION OF SITE: lot 24 Brookglen PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-6	GR/wsbk scl	FRI SSSP					
	6-17	MWSBK RCL	FRI SS SP	few Inc of SAP				
	17-60	WFSBK/MBK RCL	FI SSSP	common YB motels		wetness @ 24"		4
				few 2chroma				
	0-12	Compacted CL/C VFI						
	12-56	WFSBK BRCL FRI SSSP		few Inc of SAP				PS 3
	0-6	gr loam sbk SSSP						PS 3 @ 25"
	6-15	SBK loam C fr SSSP						
	15-52	wbk C L sandy loam/sandy C L fr SP						
	52-58	yb/rd sc common mot SP fr SP - wetness?						
	0-11	Compacted CL/C VFI						
	11-55	RBCLC w WFSBK FRI SSSP		Few YB Motels Inc f RBCK		@ 24"		PS .25 @ less than 48"

ESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ıle Space (.1945)		
Type(s)		
AR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____