DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED 2-28-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 87 Sec 2 Brookhaven PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-4	brn scl fr ssgr		few 14" common manganese			maybe LPP	(4)
		4-20	wk sbk brn scl fr sp						
		20-56	wk mb yb-gy fsl scl fr sp mica						
2		0-5	gr brn scl fr						
		5-16	mb sbk brn scl fr sp		common manganese				
		16-36	scl common fr sp		30"				(4)
3		0-3	BSCL GR fr SSSP						
		3-28	RB C fr SP						(4)
		28-46	GRVL SC fr SP/MSP w/ BOULDERS		2 chroma 21"+				
4		0-9	gr brn SL/scl						LPP .1-.05
		9-35	wk sbk brn scl fr SSSP		mixed common manganese 28"+				
		35-54	MB mbk scl fr SSSP soapstone						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

(5) 0-16 RC SBK fr SSSP
16-56 RCL MSBK fr SSSP - common SAP (3)