STEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

NER: _____ APPLICANT: _____

DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____

OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

CATION OF SITE: lot 85 Brookside PROPERTY RECORDED: _____

ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut 3) No structure / possible fill

PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed (M)

	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
		0-4	wsgr BR cl	fr: SSSP					
		4-30	PBK/SBK lc	fr/fi: SSSP					
1		30-56	YBCl wsgr	fr: SSSP	common YB mottles @ 44-48" deep				.25 @ less than 44"
		0-24	SBK/gran FL	fri: SSSP					
2		24-58	SBK B/RCl	fri/SSSP	common RBMCl/YB mottles system deep				.25
		0-6	WSBK lc	fr: SSSP					~.5
3		6-29	RC PBK	fr: SP	few YB mottles				.45
		29-60	sl SBK	fr: SSSP	system deep				.3
(4)		0-18	cl SAP m/WSBK	fri/fi:	SP — (W) — possible 2 chromas				.3 @ > 18"
		18-62	sl SAP m	fr: MSNP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
tem Type(s)		
: LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____