...ISION OF ENVIRONMENTAL HEALTH:
-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

...ER: _____ APPLICANT: _____
DRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 4-1-05
)POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: lot 21 Brook Glen PROPERTY RECORDED: _____
TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
'E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-6	comp fill cl						PS .3-.4
	6-20	mfsbk heavy cl	fri sssp					
	20-43	mfsbk heavy cl	fri sssp					
	43-60	L mdsap	fri sssp					
	0-18	GR/mSBK LSCL	FRI SS SP					PS .3+
	18-32	SBK RSCL	FRI SS SP					
	32-48	mwSBK RCL	FRI SS SP	In of SAP				
	48-61	L SAP	FRI SS SP/NP					
	0-5	GR/mSBK LSCL	FRI SS SP					PS .4
	5-24	SBK RCL	FRI SS SP					
	24-43	WF SBK BRL SAP	FRI SS SP					
	43-61	F SL SAP	FRI SS NP					
	0-17	SAB RC	fri sssp					B .3+
	17-28	mfsbk cl	common lds sssp					
	28-58	wet cl	common lds sssp					

ESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
...le Space (.1945)		
Type(s)		
AR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____